Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE4109/1
Work Order Type: Weatherization
Audit Name: Audit (247)

CLIENT INFORMATION

Client Name: Address:

Client ID: 50005DE4109 , TN

Alt. Client ID:

AGENCY INFORMATION

Agency: Delta Human Resource Agency

Agency Phone: (901) 476-5226

Address: P. O. Box 634 **Fax:** (901) 476-5258

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Page 1 of 5

Measures

	Measure 1 Infil	tration Redctn			Componen	ts		1	Inspected
C		e Threshold at Front Door weep Rear Door	r; Weather	strip R	ear, Side1 a	and Side2	2 Doors	·,	
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 2 DW	H Pipe Insulation			Componen				Inspected
C	comment	·	Unito		Estimated		Ofty	Actual	
<i>C</i>		H Pipe Insulation Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	•		Qty		Inspected Total
# 1	Comment Material / Labor	Description / Comment		Qty	Estimated		Qty	Actual	
c # 1	Comment Material / Labor Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
c # 1	Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
c # 1	Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
c # 1	Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated			Actual	

	<i>Measure</i> 3 DW	H Tank Insulation			Componen	ts			Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
(Other Detail						1		
L									
]		
				Measur	e Sub Total:			Sub Total:	
	Measure 4 Atti	ic Ins. R-11			Componen				Inspected
C	comment		Units		Estimated	1	Ofv	Actual	
<i>C</i>		Description / Comment Attic Insulation - Blown Cellulose - R-11	<i>Units</i> SqFt	Qty 1248	-		Qty		Inspected Total
C #	Comment Material / Labor	Description / Comment Attic Insulation - Blown		Qty	Estimated	1	Qty	Actual	
C #	Comment Material / Labor Insulation	Description / Comment Attic Insulation - Blown		Qty	Estimated	1	Qty	Actual	
C #	Comment Material / Labor Insulation	Description / Comment Attic Insulation - Blown		Qty	Estimated	1	Qty	Actual	
C #	Comment Material / Labor Insulation	Description / Comment Attic Insulation - Blown	SqFt	Qty 1248	Estimated	1		Actual	
C #	Comment Material / Labor Insulation	Description / Comment Attic Insulation - Blown	SqFt	Qty 1248	Estimated Unit Cost	1		Actual Unit Cost	

Report Run On: 5/28/2010

		m Windows			Componen	ts WD9			Inspected
C	omment				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window	SqFt	11.56					
2	Labor	Storm Window	SqFt	11.56					
3	Other	Storm Window	Each Window	1					
C	Other Detail								
				Moasura	Sub Total:]	Sub Total:	
	Measure 6 CO I	Monitor is Needed			Componen				Inspected
С	omment				Estimated	,		Actual	
C	omment Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected Total
C	omment		<i>Units</i> Each		Estimated	,	Qty	Actual	
C # 1	omment Material / Labor Health and Safety	Description / Comment		Qty	Estimated	,	Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items	Description / Comment CO monitor	Each	Qty 1	Estimated	,	Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	,	Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	,	Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Hour	1 1	Estimated	,		Actual	
c # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Hour	1 1	Estimated Unit Cost	,		Actual Unit Cost	

Measure 7 Fix	Gas Leak Present (Coo	k Stove)		Componen	ts		ı	nspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	/ Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
				_				
<i>Measure</i> 8 Fix Far	Improper Venting Kitch	en Exhau	st	Componen	ts		'	nspected
Comment	•							
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	/ Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:				e Sub Total:		J	Sub Total:	

Report Run On: 5/28/2010